



Situation 14.5.2018


D1 OK

D2 OK

D3 OK

Driven Element OK

Ref OK



Situation 11.07.2018

D1 OK

D2 OK

D3 OK

Driven Element OK

Ref OK

«swinging» element filmed

Info sent to GOKSC

12.7.2018

[Das schwingende Element](#)

Situation

10.11.2018

D1 OK

D2 ½ lost

D3OK

Driven Element OK

Ref ½ lost



4.11.2018 Info to G0KSC about «missing» elements

5.11.2018 Info from G0KSC that the phenomenon is known for such antennas

10.11.2018 start of investigations to that problem


12.11.2018 Info from W7EW to use ropes

Different trials of materials to damp the “swinging” elements

[Test setup](#)

>> Best Solution for the actual tubes is a 5mm rope.

Waiting for possibility to take down the antenna.



Situation 13.5.2019

D1 lost

D2 ½ lost

D3OK


Driven Element OK

Ref ½ lost


4.6.2019 Analyses and Repair of the 6m LFA

D1 complete pull out from the boom.

The first hollow rivet was pulled because the boom ends «too early».




The 2 hollow rivets of D3 were shortly before pulled out of the boom.




>> Decision to fix all elements thru the boom and secure with safety nut. Add material to strengthen the boom at both ends.


Modification




Three tubes
inserted to
reinforce the
boom.



D1 Repair




Reinforcement of the reflector side. Here the hollow rivets are still present so I could not use tubes to insert.



5mm rope inserted to all elements.

[Without a rope over 30s:](#)

[With a rope over 30s:](#)



Antenna again ready to be mounted to our QTH on the Weissenstein for many DX. Thanks for support from you all!

